


4350 CABINET BRACING #3 - CABINET REAR VIEW



VERY EARLY 4350'S HAD THE BACK BRACING SCREWED FROM THE OUTSIDE, THRU THE BACK AND INTO THE BRACE. ON THOSE MODELS THE PHILLIPS HEAD SCREWS ARE VISIBLE ON THE BACK. LATER MODELS HAD THE BRACES SCREWED FROM THE INSIDE AND THERE IS NOTHING VISIBLE ON THE BACK PANEL.